

Vehicle report: The Wagon

Vehicle	2019 Subaru Outback Premium	Plate	7XKD213
Powertrain	ICE	Odometer	53,203 mi as of 2026-09-10
Purchased	2024-03-24		

Overview

Distance, total	12,086 mi	Last 12 months	7,582 mi
Fuel economy	32.6 mpg	Last service	2026-08-01 Oil and filter change
Records	5 service, 24 fuel/charge, 1 odometer, 2 other		

Currency	Last 30 days	Last 12 months	Lifetime
USD	62.00 USD	2691.36 USD	3471.76 USD

Spend by category, last 12 months	Amount
fuel	1207.96 USD
insurance	612.00 USD
repair	412.00 USD
service	372.90 USD
registration	86.50 USD

Upcoming maintenance

Reminder	Due	
Replace wiper blades	2026-09-29	
Engine oil and filter	2026-10-23 54,871 mi	
Tire rotation	2026-10-23 54,871 mi	
Warranty ends: Front wheel bearing	2026-10-25	
State inspection	2026-12-04	
Insurance expires: Auto insurance, six months	2026-12-17	
Registration expires: Registration renewal	2027-01-13	
Brake fluid flush	2027-02-27	
Cabin air filter	2027-04-23 62,327 mi	
Engine air filter	2027-04-23 68,541 mi	
Warranty ends: Battery, 36-month replacement	2028-08-15	
Warranty ends: Gold Plus extended coverage	2029-01-27 100,000 mi	
Coolant service	103,254 mi	

Open recalls

Campaign	Component	Summary
----------	-----------	---------

Campaign	Component	Summary
19V493000	STRUCTURE	Subaru of America, Inc. (Subaru) is recalling certain 2019 Legacy and Outback vehicles. Spot welds located on the duct below the cowl panel may have been improperly applied, impacting the vehicle's body strength.
20V218000	FUEL SYSTEM, GASOLINE:DELIVERY:FUEL PUMP	Subaru of America, Inc. (Subaru) is recalling certain 2019 Impreza, Outback, Legacy, and Ascent vehicles. The low pressure fuel pump may become inoperative.
21V587000	FUEL SYSTEM, GASOLINE:DELIVERY:FUEL PUMP	Subaru of America, Inc. (Subaru) is recalling certain 2019-2020 Ascent, 2018 Forester, 2018-2020 Impreza, Legacy, Outback, 2018-2019 BRZ, WRX, and Toyota 86 vehicles. The low-pressure fuel pump inside the fuel tank may fail.

Warranties in force

Warranty	Kind	Expires	Or at
Front wheel bearing	part	2026-10-25	
Battery, 36-month replacement	part	2028-08-15	
Gold Plus extended coverage	extended	2029-01-27	100,000 mi

Expiring soon

Item	Type	Expires
Front wheel bearing	warranty	2026-10-25

Cost of ownership

Purchase price	24500.00 USD	Total spend	3471.76 USD
Distance	14,803 mi	Per month	115.16 USD
Per mi	0.23 USD		

Category, since purchase	Total
cost:insurance	612.00 USD
cost:registration	86.50 USD
service:repair	412.00 USD
service:service	372.90 USD
service:upgrade	279.00 USD
energy:fuel	1709.36 USD

Service records

2025-02-27 Roof rack crossbars

Kind	upgrade	Odometer	41,117 mi
Cost	279.00 USD		

2025-10-25 Front wheel bearing replacement

Kind	repair	Odometer	46,188 mi
Cost	412.00 USD		

2026-02-12 Tire rotation and brake inspection

Kind service **Odometer** 48,512 mi
Cost 45.00 USD

2026-04-23 Engine oil and filter, Tire rotation, Cabin air filter, Engine air filter

Kind service **Odometer** 49,900 mi
Cost 238.40 USD **Tags** filter, oil, tires

Work done Cabin air filter, Engine air filter, Flat repair, Fuel filter, Oil change (no filter), Oil & filter change, Tire replacement, Tire rotation, TPMS sensor, Wheel alignment, Wheel balance

Notes Caught up on everything the schedule listed.

2026-08-01 Oil and filter change

Kind service **Odometer** 52,103 mi
Cost 89.50 USD

Tires

Position	Tire	Age	Min tread	Distance	Alerts
LF	Michelin CrossClimate2		5.9 mm	14,803 mi	
RF	Michelin CrossClimate2		5.7 mm	14,803 mi	
LR	Michelin CrossClimate2		6.4 mm	14,803 mi	
RR	Michelin CrossClimate2		6.2 mm	14,803 mi	
SPARE	Michelin CrossClimate2			14,803 mi	

Insurance, registration & fees

Date	Title	Kind	Expires	Amount	Policy
2026-06-17	Auto insurance, six months	insurance	2026-12-17	612.00 USD	
2026-01-13	Registration renewal	registration	2027-01-13	86.50 USD	